



**KOBELCO INTERNATIONAL (S) CO., PTE. LTD.**

30 PIONEER CRESCENT,

#03-15 WEST PARK BIZCENTRAL,

SINGAPORE 628560

**KOBELCO CONSTRUCTION MACHINERY INTERNATIONAL TRADING CO., LTD.**

7-15, Minatojima, Chuo-ku, Kobe City, Hyogo

Postal Code: 650-0045 Japan

BULLETIN NO: 007-7055-3F-#0013-22

**KOBELCO USED CRAWLER CRANE**



**MODEL:** Kobelco 7055-3F  
**CAPACITY:** 55t  
**Y.O.M.:** 2016  
**S/NO:** GBA1-00013  
**ENGINE HRS:** 13077  
**MAIN BOOM:** 140ft [Base Boom + 10ft + 20ft + 20ft + 30ft + 30Aft + Top Boom]  
**FIXED JIB:** 60ft [Base Jib + 20ft + 20ft + Jib Top]  
**HOOK BLKS:** 32t, 19t & Ball Hook  
**COUNTERWEIGHT** 15.2T  
**CONDITION:** Good working condition, well Maintained with New Body Paintwork  
**DELIVERY TERM:** Ex-yard Singapore  
**PRICE:** Upon Request  
**SEND INQUIRY TO:** [inquirykisco@kobelco.com](mailto:inquirykisco@kobelco.com)  
**CONTACT PERSON:**  
**Singapore:**  
[\[ANDY TAKAYAMA\] takayama.akira@kobelco.com](mailto:takayama.akira@kobelco.com) ; Mobile No: (+65) 81815977  
[\[Sam Sim\] sam.sim@kobelco.com](mailto:sam.sim@kobelco.com) ; Mobile No: (+65) 92316938

## Used crawler crane condition

### Inspection summary

Part	Evaluation
LOWER MACHINE	4.0 ★ ★ ★ ★ ☆
OPERATOR CAB	4.0 ★ ★ ★ ★ ☆
MOMENT LIMITTER	3.5 ★ ★ ★ ☆ ☆
UPPER MACHINE	4.0 ★ ★ ★ ★ ☆
ATTACHMENT	4.0 ★ ★ ★ ★ ☆
<b>Total</b>	<b>3.9 ★ ★ ★ ★ ☆</b>

#### Judgement Criteria

- ★★★★★:Close to brand new or excellent condition.
- ★★★★:Fair Workable condition under operating hrs/mileage serviced.
- ★★★:Workable condition, but minor repair is required. / Small leakage.
- ★★:Workable condition, but mager repair is required. / Middle leakage.
- ★: Non-workable, missing part. / Big leakage.



MODEL: Kobelco 7055-3F

Y.O.M.: 2016

S/NO: GBA1-00013

### Conclusion & Comments

#### Conclusion & Comments

Overall, above machine is clean and tidy, the crane control system is in order as manufacture standard, the electrical circuit such as Moment limiter and gauge cluster is in good condition. Crane operation performance is excellen t condition, no abnormal found during machine inspection.

#### Conducted the machine rectification

Engine full servicing, change Crankshaft seal front and rear  
 Refurbish fuel line system  
 Replaced engine oil and filters element  
 Replaced hydraulic filters  
 Under carriage has been rebuild such as Tumbler sprocket, Idler, Rollers, and guide bar and track shoes as manufacture guidan ce.  
 Replaced damage upper rollers  
 Replaced boom hoist wire rope, Front drum wire rope and Rear drum wire rope  
 Reseal gantry hydraulic cylinder  
 New painting  
 Check and refill oil lubricant for reduction components  
 Replaced sheaves bearing from top boom  
 Replaced load detector with calibration

#### ~Remarks~

- This document reflects the condition of this crane at the time of inspection to the best of our ability.
- We will not be held accountable for any liabilities, from this machine condition report.
- Please contact us for the viewing and inspection arrangement of the machine.

## Photos





