



KOBELCO INTERNATIONAL (S) CO., PTE. LTD.

30 PIONEER CRESCENT,
#03-15 WEST PARK BIZCENTRAL,
SINGAPORE 628560

KOBELCO CONSTRUCTION MACHINERY INTERNATIONAL TRADING CO., LTD.

7-15, Minatojima, Chuo-ku, Kobe City, Hyogo
Postal Code: 650-0045 Japan

BULLETIN NO: 007-7055-3F-#0014-22

KOBELCO USED CRAWLER CRANE



MODEL:	Kobelco 7055-3F
CAPACITY:	55t
Y.O.M.:	2016
S/NO:	GBA1-00014
ENGINE HRS:	13448
MAIN BOOM	140ft [Base Boom + 10ft + 20ft + 20ft + 30ft + 30Aft + Top Boom]
FIXED JIB	60ft (Base Jib + 20ft + 20ft + Jib Top)
HOOK BLKS:	32t, 19t & Ball Hook
Counterweight	15.2T
CONDITION:	Good working condition, well Maintained with New Body Paintwork
DELIVERY TERM:	Ex-yard Singapore
PRICE:	Upon Request
SEND INQUIRY TO:	inquirykisco@kobelco.com
CONTACT PERSON:	
Singapore:	
	[ANDY TAKAYAMA] takayama.akira@kobelco.com ; Mobile No: (+65) 81815977
	[Sam Sim] sam.sim@kobelco.com ; Mobile No: (+65) 92316938

Used crawler crane condition

Inspection summary

Part	Evaluation
LOWER MACHINE	4.0 ★ ★ ★ ★ ☆
OPERATOR CAB	4.0 ★ ★ ★ ★ ☆
MOMENT LIMITTER	4.0 ★ ★ ★ ★ ☆
UPPER MACHINE	4.0 ★ ★ ★ ★ ☆
ATTACHMENT	4.0 ★ ★ ★ ★ ☆
Total	4.0 ★ ★ ★ ★ ☆

Judgement Criteria

- ★★★★★:Close to brand new or excellent condition.
- ★★★★:Fair Workable condition under operating hrs/mileage serviced.
- ★★★:Workable condition, but minor repair is required. / Small leakage.
- ★★:Workable condition, but mager repair is required. / Middle leakage.
- ★: Non-workable, missing part. / Big leakage.



MODEL: Kobelco 7055-3F

Y.O.M.: 2016

S/NO: GBA1-00013

Conclusion & Comments

Conclusion & Comments

Overall, above machine is clean and tidy, the crane control system is in order as manufacture standard, the electrical circuit such as Moment limiter and gauge cluster is in good condition. Crane operation performance is excellent condition, no abnormal found during machine inspection.

Conducted the machine rectification

Engine full servicing, change Crankshaft seal front and rear

Replaced engine oil and filters element

Replaced hydraulic filters

Under carriage has been rebuild such as Tumbler sprocket, Idler, Rollers, and guide bar and track shoes as manufacture guidance.

Reseal gantry hydraulic cylinder

New painting

Check and refill oil lubricant for reduction components.

~Remarks~

- This document reflects the condition of this crane at the time of inspection to the best of our ability.
- We will not be held accountable for any liabilities, from this machine condition report.
- Please contact us for the viewing and inspection arrangement of the machine.

Photos





