



KOBELCO INTERNATIONAL (S) CO., PTE. LTD.

30 PIONEER CRESCENT,

#03-15 WEST PARK BIZCENTRAL,

SINGAPORE 628560

KOBELCO CONSTRUCTION MACHINERY INTERNATIONAL TRADING CO., LTD.

7-15, Minatojima, Chuo-ku, Kobe City, Hyogo

Postal Code: 650-0045 Japan

BULLETIN NO: 008-BM800HD-#3012-22

KOBELCO USED CRAWLER CRANE



MODEL: Kobelco BM800HD-2F

CAPACITY: 80t

Y.O.M.: 2007

S/NO: GD04-03012

ENGINE HRS: 30299

MAIN BOOM 140ft [Base Boom + 10ft + 30ft + 30ft + 30Aft + Top Boom]

HOOK BLKS: 32t & Ball Hook

CONDITION: Main, Auxiliary & Third winches, with Translifter, with two pulley Auxiliary sheaves

Good working condition, well Maintained with New Body Paintwork

DELIVERY TERM: Ex-yard Singapore

CONTACT PERSON in Singapore

[\[ANDY TAKAYAMA\]](#) takayama.akira@kobelco.com ; Mobile No: (+65) 81815977

[\[Sam Sim\]](#) sam.sim@kobelco.com ; Mobile No: (+65) 92316938

Used crawler crane condition

Inspection summary

Part	Evaluation
LOWER MACHINE	4.0 ★ ★ ★ ★ ☆
OPERATOR CAB	4.0 ★ ★ ★ ★ ☆
MOMENT LIMITTER	4.0 ★ ★ ★ ★ ☆
UPPER MACHINE	4.0 ★ ★ ★ ★ ☆
ATTACHMENT	4.0 ★ ★ ★ ★ ☆
Total	4.0 ★ ★ ★ ★ ☆

Judgement Criteria

- ★★★★★:Close to brand new or excellent condition.
- ★★★★:Fair Workable condition under operating hrs/mileage serviced.
- ★★★:Workable condition, but minor repair is required. / Small leakage.
- ★★:Workable condition, but mager repair is required. / Middle leakage.
- ★: Non-workable, missing part. / Big leakage.



MODEL: Kobelco BM800HD-2F

Y.O.M.: 2009

S/NO: GD04-03047

Conclusion & Comments

The overall machine operation and performance is satisfactory as manufacture standard, cabin operation control levels and switches are in proper located and functioning. Safety devices such as moment limiter indication, over hoist limit, Anti two block with auto cut off is functioning work in excellent condition, limit switch extension cable reel harness is proper located.
Excellent condition for all hoist drum performance such as free fall function.

~Remarks~

- This document reflects the condition of this crane at the time of inspection to the best of our ability.
- We will not be held accountable for any liabilities, from this machine condition report.
- Please contact us for the viewing and inspection arrangement of the machine.

Photos







