KOBELCO INTERNATIONAL (S) CO., PTE. LTD.

No 10, Tuas Avenue 5. SINGAPORE 628560 **KOBELCO CONSTRUCTUION MACHINERY INTERNATIONAL TRADING CO., LTD.** 7-15, Minatojima, Chuo-ku, Kobe City, Hyogo Postal Code: 650-0045 Japan

BULLETIN NO: UCB0020-CKS900-#03382-24 KOBELCO USED CRAWLER CRANE



MODEL:	Kobelco CKS900
CAPACITY:	90T
Y.O.M.:	2014
S/NO:	GN04-03382
ENGINE HRS:	22700
SPECIFICATION:	170ft (51.8m) Main Boom plus 60ft (18.3m) Fixed Jib
HOOK BLKS:	70t, 35t & Ball Hook
Counterweight	46.3t
CONDITION:	Re-Furbished, Good working condition, well Maintained with New Body Paintwork
DELIVERY TERM:	Ex-yard Singapore
CONTACT PERSON:	

達城 仁[Hitoshi_TATSUSHIRO] <tatsushiro.hitoshi@kobelco.com> Mobile No: (+81) 80-8347-9424 阿斯亜[Suya_A] <a.suya@kobelco.com> Mobile No: (+65) 90886722 / (+81) 80-8345-9813 [Sam Sim] <sam.sim@kobelco.com> Mobile No: (+65) 92316938

Used Crawler Crane Condition

Inspection summary

Total	4.0 ★★★★☆
ATTACHMENT	4.0 ★★★★☆
UPPER MACHINE	4.0 ★★★★☆
MOMENT LIMITTER	4.0 ★★★★☆
OPERATOR CAB	4.0 ★★★★☆
LOWER MACHINE	4.0 ★★★★☆

Judgement Criteria

 $\star \star \star \star \star$: Close to brand new or excellent condition.

 $\star \star \star \star$:Good Working condition under operating hrs/mileage serviced.

 $\star \star \star$:Workable condition, but minor repair is required. / Small leakage.



MODEL: Kobelco CKS900 Y.O.M.: 2014 S/NO: GN04-03382

Conclusion & Comments

The overall machine is clean and tidy, the crane control system is in order as manufacture standard, the electrical circuit such as Moment limiter and gauge cluster is in good condition. Crane operation performance is excellent condition, no abnormal found during machine inspection.

~Remarks~

This document reflects the conditon of this crane at time of inspection to the best of our ability. We will not be held accountable for any liabilities., for this machine condition report. Please contact us for arrangements for the viewing and inspection of the machine.

<u>Photos</u>





