KOBELCO INTERNATIONAL (S) CO., PTE. LTD.

KOBELCO CONSTRUCTUION MACHINERY INTERNATIONAL TRADING CO., LTD.

No 10, Tuas Avenue 5. SINGAPORE 628560

7-15, Minatojima, Chuo-ku, Kobe City, Hyogo

Postal Code: 650-0045 Japan

BULLETIN NO: UCB0022-CKE1100-#3439-24

KOBELCO USED CRAWLER CRANE



MODEL: Kobelco CKE1100

CAPACITY: 110T **Y.O.M.:** 2011

S/NO: GK04-03439

ENGINE HRS: 22700

SPECIFICATION: 200ft (61m) Main Boom plus 70ft (21.3m) Fixed Jib

HOOK BLKS: 70t, 35t & Ball Hook

Counterweight 34t

CONDITION: Re-Furbished, Good working condition, well Maintained with New Body Paintwork

DELIVERY TERM: Ex-yard Singapore

CONTACT PERSON:

達城 仁[Hitoshi_TATSUSHIRO] <tatsushiro.hitoshi@kobelco.com> Mobile No: (+81) 80-8347-9424

阿斯亜[Suya_A] <a.suya@kobelco.com> Mobile No: (+65) 90886722 / (+81) 80-8345-9813

[Sam Sim] <sam.sim@kobelco.com> Mobile No: (+65) 92316938

Used Crawler Crane Condition

Inspection summary

OPERATOR CAB	4.0 ★★★★☆
MOMENT LIMITTER	4.0 ★★★★☆
UPPER MACHINE	4.0 ★★★★☆
ATTACHMENT Total	4.0 ★★★★☆
Total	4.0 ★★★★☆



MODEL: Kobelco CKE1100

Y.O.M.: 2011

S/NO: GKO4-03439

Judgement Criteria

 $\star\star\star\star$: Close to brand new or excellent condition.

 $\star\star\star\star$:Good Working condition under operating hrs/mileage serviced.

 $\star\star$:Workable condition, but minor repair is required. / Small leakage.

Conclusion & Comments

The overall machine is clean and tidy, the crane control system is in order as manufacture standard, the electrical circuit such as Moment limiter and gauge cluster is in good condition. Crane operation performance is excellent condition, no abnormality found during machine inspection.

This document reflects the condition of this crane at time of inspection to the best of our ability. We will not be held accountable for any liabilities., for this machine condition report. Please contact us for arrangements for the viewing and inspection of the machine.

Photos



